


PME 9 with Remote Supervisory

S = Switch, F = Fuse



PME Model #	A	B	C	D	E	F	G	H
9 w/ RS	25' 10"	18' 3"	10'	5' 10"	10'	6'	6' 3"	6'